

Flood Control Project Maintenance**2013 Channel Summary Report****Overall Unit and Item Ratings****Adin Community Service District**

Ash Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Dry Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Flood Control Project Maintenance
2013 Channel Summary Report
Overall Unit and Item Ratings

DWR Sutter Maintenance Yard

Big Chico Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Lindo Channel & Sandy Gulch

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Little Chico Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Flood Control Project Maintenance
2013 Channel Summary Report
Overall Unit and Item Ratings

Fairfield Suisun Sewer District

Laurel Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | U |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Ledgewood Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

McCoy Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Union Avenue Diversion

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Flood Control Project Maintenance
2013 Channel Summary Report
Overall Unit and Item Ratings

Madera County FCWCA

Ash Slough

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | N |
| | Encroachments | A |

Berenda Slough

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| U | Vegetation & Obstructions | U |
| | Shoaling / Sedimentation | U |
| | Erosion / Bank Caving | U |
| | Revetments & Other Structural Appurtenances | U |
| | Encroachments | M |

Chowchilla River

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | N |
| | Encroachments | A |

Fresno River

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | U |
| | Shoaling / Sedimentation | U |
| | Erosion / Bank Caving | M |
| | Revetments & Other Structural Appurtenances | M |
| | Encroachments | A |

Flood Control Project Maintenance
2013 Channel Summary Report
Overall Unit and Item Ratings

Merced Streams Group

Bear Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | M |
| | Revetments & Other Structural Appurtenances | M |
| | Encroachments | A |

Black Rascal Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | M |
| | Erosion / Bank Caving | M |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | M |

Burns Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | N |
| | Encroachments | A |

Mariposa Creek & Duck Slough

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | M |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Miles Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Owens Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | M |

Flood Control Project Maintenance
2013 Channel Summary Report
Overall Unit and Item Ratings

Placer County

Truckee River

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Flood Control Project Maintenance**2013 Channel Summary Report****Overall Unit and Item Ratings****San Joaquin County Flood Control and Water Conservation District****Duck Creek Diversion Channel**

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

North Littlejohn Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | M |

South Littlejohn Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| M | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | M |

South Littlejohn Creek North Branch

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | M |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |

Flood Control Project Maintenance**2013 Channel Summary Report****Overall Unit and Item Ratings****Tehama County Flood Control and Water Conservation District**

McClure Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | M |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | N |
| | Encroachments | A |

Salt Creek

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---|-------------|
| A | Vegetation & Obstructions | A |
| | Shoaling / Sedimentation | A |
| | Erosion / Bank Caving | A |
| | Revetments & Other Structural Appurtenances | A |
| | Encroachments | A |